

MEI VNR Machine Compatibility - 26 July 2010

PLEASE NOTE: If \$20 note acceptance is required, please change the Recycler interface to L2

This list represents the machines that have been tested by MEI. If you do not see your particular machine on this list, it does not mean that the MEI Recycler will not work. It only means that it was not tested.

<u>Machine Type</u>	<u>Control Bd Software</u>	<u>VN2700R fit and function</u>	<u>VFM Bezel (NEW)</u>	<u>Compact Bezel</u>	<u>VFM High Vis Bezel</u>	<u>Compact High Vis Bezel</u>	<u>Notes for Recycler</u>
Dixie Narco							
DN 501E (w/electronic lock - NON HVV)		No	No	No	No	No	Function OK. Electronic lock makes fit impossible.
DN 501E (SIID Controller)	381.41	Yes	Yes	No	Yes	No	
DN 501HVV (Pepsi)	240.61	Yes	Yes	No	Yes	No	Remove blue bracket between the Coin Changer and the Recycler.
DN501 E (SII Controller)	804.907.780.11	No function - Fit is OK	N/A	No	N/A	No	Will not enable notes on this version.
DN 276EMC/S2-7 (SII Controller)	381.31	No	N/A	N/A	N/A	N/A	
Dixie Narco 501ER SIID - REFURB Machine	381.41	Yes	Yes	Yes	Yes	Yes	
DN5591 Glass front	30.61, 30.81	Yes	Yes	No	Yes	No	
Dixie / ECC Bottle Drop	V030.81	Yes	Yes	No	Yes	No	Use MDB Level 2 only
DN756P HVV (Pepsi)	V871.01	Yes	Yes	No	Yes	No	Use MDB Level 2 only when recycling \$5s.
DN700 CV	510.71D	Yes	Yes	No	Yes	No	
DN5800 Glass Front Bev Max 3	80.61D	Yes	Yes	No	Yes	No	
DN5800 Glass Front Bev Max 4 Coke	Version 700.61	Yes	Yes	Yes	Yes	Yes	
DN5800 Glass Front Bev Max 4 Pepsi / Generic	Version 700.61 - EVS 3.1	Yes	Yes	Yes	Yes	Yes	
Vendo							
Vendo 701	VEC 5.1 - V1062, V1063 - VMC made by MEI	Yes	Yes	No	Yes	No	MUST be in MDB Level 2 when accepting \$20. Level 3 is OK with \$1 - \$10.
Vendo 701 (Coke)	VEC 5.2 - EVS (Coke)	Yes	Yes	No	Yes	No	MUST be in MDB Level 2 when accepting \$20. Level 3 is OK with \$1 - \$10.
Vendo 720	VEC 9.1 - V2.050	Yes	Yes	No	Yes	No	MUST be in MDB Level 2 when accepting \$20. Level 3 is OK with \$1 - \$10.
Vendo HVV 721 (Pepsi)	VEC 12.3 - V3.014, V 2.040	Yes	Yes	No	Yes	No	NOTE: May have to move steel brace (rib) to mount recycler.
Vendo HVV 821P, 840D (Pepsi)	VEC 12.3 - V3.014, V 2.040	yes	no	Yes	no	Yes	NOTE: May have to move steel brace (rib) to mount recycler.
Vendo 603	Vec 9.2	Yes	Yes	No	Yes	No	

<u>Machine Type</u>	<u>Control Bd Software</u>	<u>VN2700R</u> <u>fit and</u> <u>function</u>	<u>VFM</u> <u>Bezel</u> <u>(NEW)</u>	<u>Compact</u> <u>Bezel</u>	<u>VFM High</u> <u>Vis Bezel</u>	<u>Compact</u> <u>High Vis</u> <u>Bezel</u>	<u>Notes for Recycler</u>
Vendo Vue Generic Glassfront	VEC 15.1 Rev 1.45	Yes	Yes	No	Yes	No	Must use MDB level 2 for \$20 notes.
Vendo 721 cold drink generic	VEC 12.1 Rev 1.15	Yes, but contact MEI before you install on this machine.	Yes	No	Yes	No	Contact MEI before installing in this machine.
Vendo 721 cold drink generic	VEC 12.1 Rev 24	Yes	Yes	No	Yes	No	Must use MDB level 2 for \$20 notes.
Vendo 601	Vec 5.1 - V1.068 VMC made by Versitile Controls.	No	n/a	n/a	n/a	n/a	
Royal							
Royal GII	67036-11	Yes	Yes	No	Yes	No	No \$20 acceptance. OK for all else.
RV660-9 GIII	(GIII) 67015-4,67015-5, 67015-6, 67015-8,67131-3, 67131-6, 67131-5, 67121-6	Yes	Yes	No	Yes	No	Must remove metal security bracket.
Royal 550 KO	(KO) 67131-6, 67265.5	Yes	Yes	No	Yes	No	Check security bracket, remove if necessary.
RV804 GIII	67121-2, 67121-3, 67121-4, 67121-6, 67121-7, 67131-2, 67131-5, 67015-4, 67015-8, 67015-9	Yes	Yes	No	Yes	No	Check security bracket, remove if necessary.
RV500-40 Glassfront		Yes	Yes		Yes		
RV660-KO	67131-6	Yes	Yes		Yes		
RV660-KO	67131-6	Yes	Yes		Yes		
RVCC-804-9	67121-7, 67015-6, 67121-2, 67121-4, 67121-3evs, 67121-4evs, 67015-4, 67121-7evs, 67121-3, 67015-8	Yes	Yes	no	Yes		
RV780-9(EVS)		Yes			Yes		
Royal 804 Market Vendor GIII		No					Remove Bill Guard Plate to make the VNR fit
Royal 804-13(EVS)		Yes	Yes	No	Yes		Must remove Middle BV Plate
Royal 500-64	67241-6, 67246-5, 67246-7	Yes	yes	yes	Yes	Yes	Must remove splash plate above display.
Royal - RVRW- 500 (Coke)	67241-6	Yes	yes	yes	Yes	Yes	Must remove splash plate above display.
Royal RVRW-600 (Coke)	67246-6	Yes					
Royal 500	67246-4	Yes	Yes	Yes	Yes	Yes	recycling \$1 and accepting a \$20 for 50c vend. Machine pays out \$10.75 and then \$8.75 in level 3. Passed the \$20 in and 3 minute wait. Level 2 test...OK
RVCDE-650-10 or any machine with the Merlin IV control board	67100-10, 67100-12	Yes	Yes	no	Yes	no	Must have recycler set to level 2 only.

<u>Machine Type</u>	<u>Control Bd Software</u>	<u>VN2700R</u> <u>fit and</u> <u>function</u>	<u>VFM</u> <u>Bezel</u> <u>(NEW)</u>	<u>Compact</u> <u>Bezel</u>	<u>VFM High</u> <u>Vis Bezel</u>	<u>Compact</u> <u>High Vis</u> <u>Bezel</u>	<u>Notes for Recycler</u>
Royal Merlin III Controller	67237-07, V11.06	Yes	Yes	no	Yes	no	Recycler must be in level 2 for \$10 and \$20 acceptance.

<u>Machine Type</u>	<u>Control Bd Software</u>	<u>VN2700R</u> <u>fit and</u> <u>function</u>	<u>VFM</u> <u>Bezel</u> <u>(NEW)</u>	<u>Compact</u> <u>Bezel</u>	<u>VFM High</u> <u>Vis Bezel</u>	<u>Compact</u> <u>High Vis</u> <u>Bezel</u>	<u>Notes for Recycler</u>
<u>Crane National Vendors</u>							
Crane model 159	v160.07	Yes	Yes	No	Yes	No	Level 2 only. Must enable high denomination notes on Vendor controller.
National 167	158.18, 158.22, 158.23	Yes	Yes	No	Yes	No	
National 432 Cold Food	432.05	Yes	Yes - no setback needed.	No	Yes - no setback needed.	No	Functions well in MDB Level 2 or 3.
National 168	158.22	Yes					
National 797		Yes					
National 168	158.21, 158.14	Yes					
National 167	0.005; 158.23	Yes	Yes		Yes		
National 455	0.005	Yes					
Merchant 6 - 181C	181.02.00		Yes		Yes		
National 675D	673.042	Yes	Yes				
GPL / Crane Model 173 Snack	V 160.09	Yes	Yes	No	Yes	No	Must enable all \$5, \$10 and \$20 on machine. This machine can only do level 2. Set recycler in level 2 only.
GPL / Crane Model 427 Cold Food	V 427.03	Yes**	Yes	No	Yes	No	**This Machine cannot accept \$10s or \$20s. This is a machine limitation. Can only recycle \$1s and accept \$2s and \$5s. Level 2 only machine. Machine tries to manage change and will sometimes payout lots of quarters when ones get low. Eventually it will pay out all of the ones.
Crane National 431D Cold Food machine Also called the Shoppertron.	N/A	No Fit	N/A	N/A	N/A	N/A	Cannot fit. Payment system door will not close.
Crane National 167 Snack	Version 158.21	Yes	Yes, with setback and extender nuts.	No	Yes, with setback and extender nuts.	No	Must enable all notes on machine that you want to accept. Level 2 and Level 3 works OK. However, machine only supports level 2 change payout. Machine tries to manage change and will sometimes payout lots of quarters when \$1 notes get low. Eventually it will pay out all of the ones.
Crane / GPL 160 Snack	V 160.05	Yes	Yes	No	Yes	No	Machine is level 2 only. Must enable all \$5, \$10 and \$20 on machine. Set recycler in level 2 only. Machine tries to manage change and will sometimes payout lots of quarters when ones get low. Eventually it will pay out all of the ones.

<u>Machine Type</u>	<u>Control Bd Software</u>	<u>VN2700R</u> <u>fit and</u> <u>function</u>	<u>VFM</u> <u>Bezel</u> <u>(NEW)</u>	<u>Compact</u> <u>Bezel</u>	<u>VFM High</u> <u>Vis Bezel</u>	<u>Compact</u> <u>High Vis</u> <u>Bezel</u>	<u>Notes for Recycler</u>
Crane / GPL 160 Snack	V 160.09	Yes	Yes	No	Yes	No	Must enable all \$5, \$10 and \$20 on machine. This machine can only do level 2. Set recycler in level 2 only.
Crane Merchant 6 Snack	181.02.00 march 31, 2009 check sum 5108	Yes	Yes with setback.	No	Yes with setback.	No	Must use stud extenders when installing.

APi							
AP LCM	67061-9	Yes	Yes with setback	No	Yes with setback	No	Must use stud extenders. This machine is in level 2 (fixed).
AP LCM with InOne Technologies conversion kit	V2.71	Yes	Yes - no setback needed.	No	Yes - no setback needed.	No	
AP123	P30 04.73	Yes	Yes with setback	No	Yes with setback	No	Must use stud extenders. Must use in MDB Level 2 interface.
AP120 Snack	V5.28	Yes	Yes with setback	no	Yes with setback	No	Must use stud extenders
AP Studio Series ST 3 / 133	V22	Yes	Yes with setback	no	Yes with setback	No	Must use stud extenders.
AP Studio Series ST 2	V0020 and V0021	Yes	Yes with setback	No	Yes with setback	No	Must use stud extenders.
AP Studio Series SL	V.0068	No function	n/a	n/a	n/a	n/a	
AP Studio Series SL	V18D	No	n/a	n/a	n/a	n/a	
AP 6500 Ultra Flex Cold Food	P08 L00.23	Yes	Yes - no setback needed.	No	Yes - no setback needed.	No	Functions well in MDB Level 2 or Level 3. Cannot be used as a change machine at this time. Can only be used for purchasing.
FastCorp							
FRI-Z400 AAB	Unknown	No	No	N/A	N/A	N/A	Recycler will not fit due to the door switch bracket in the machine. Testing was done with the new style VFM bezel.
Wittern							
Wittern / USI model 3500 cold drink	N/A	Failed	Failed	Failed	Failed	Failed	No Fit at All.
Wittern/USI Older Snack	F80 Control Board	Failed	N/A	N/A	N/A	N/A	No communication with Coin Changer.
Wittern / USI model 3205 Coffee	Coffee Tech V36E	Yes *	Unknown	Unknown	Unknown	Unknown	* Function test only. Fit needs to be tried in the individual machine. Note: Machine is level 2 only. Must enable all \$5, \$10 and \$20 on machine.
Wittern/USI CV300 can bottle stand alone model 3179	MCB12 select Version 1.18	Yes*	Unknown	Unknown	Unknown	Unknown	* Function test only. Fit needs to be tried in the individual machine.
Misc machines with control board to the right.	WS5000 VN Control Board 192 Classic	Yes*	Unknown	Unknown	Unknown	Unknown	* Function test only. Fit needs to be tried in the individual machine. This machine cannot accept \$10s or \$20s.

<u>Machine Type</u>	<u>Control Bd Software</u>	<u>VN2700R</u> <u>fit and</u> <u>function</u>	<u>VFM</u> <u>Bezel</u> <u>(NEW)</u>	<u>Compact</u> <u>Bezel</u>	<u>VFM High</u> <u>Vis Bezel</u>	<u>Compact</u> <u>High Vis</u> <u>Bezel</u>	<u>Notes for Recycler</u>
Wittern/USI Model Fawn Cold Drink CB700	Fawn Cold Drink - Ver 67138-2	Yes - But will need new coin return mechanism.	Yes with setback	No	Yes with setback	No	Level 3 issue: Only \$8 change available. Still accepts a \$20 and vends. Pays out all change and then retains credit. Consumer is allowed to keep vending credit off until all credit is consumed. Level 2 or 3 is OK for normal operation.
Wittern/USI Model Snackmart VI	SM 6 Snackmart 6 67185.8 V	Yes - But will need new coin return mechanism.	Yes with setback	No	Yes with setback	No	Level 3 issue: Insert a \$20 and vend for 50c. Pays out \$11 then stops. \$8.50 remains on display. Must hit ER for balance. Change is correct, however. OK with VFM Bezel and setback. Must have new coin return mechanism. (USI part number is 1217987) May need extender nuts
Wittern/USI Model 3506 Slim Snack with Satellite re Fridgeration drink center. (Model 3506)	Global Vending Controller Lite (GVC Lite) Ver 7875	Yes - But will need new coin return mechanism.	Yes with setback	No	Yes with setback	No	OK with VFM Bezel and setback. Must have new coin return mechanism. (USI part number is 1217987) May need extender nuts
Wittern/USI Model Mercato 3000 soda and Snack with re Fridgeration (Model 3545)	Global Vending Controller 2 (GVC2) V - 2.8.8511	Yes - But will need new coin return mechanism.	Yes with setback	No	Yes with setback	No	OK with VFM Bezel and setback. Must have new coin return mechanism. (USI part number is 1217987) May need extender nuts
Wittern/USI Model 3000 Snack and drink (Model 3504 snack) (Model 3502 Drink)	Global Vending Controller 1 (GVC1) V - 8202	Yes - But will need new coin return mechanism.	Yes with setback	No	Yes with setback	No	Must use Setback Frame (included in box). You may need to use Stud Extenders. Set recycler in MDB Level 2 for optimum performance.